Shure Update Utility

2.4.8

Application architecture: 32-bit, 64-bit

Supported operating systems:

• Windows 7, 8, and 10

• macOS 10.13 (High Sierra), 10.14 (Mojave), and 10.15 (Catalina)

Processor: Intel[®]Core[™] i3, i5, or i7 equivalent, running at 2 GHz or more

System memory: 4 GB minimum; 8 GB recommended for larger system configurations

Disk space: Minimum of 40 MB of disk space required for installation

Display resolution: 1280 x 768 minimum; 1440 x 900 or better recommended

Supported languages: English

Note: Internet connection required for application download and updates, and for viewing tutorial videos and release notes.

Update Tips

- Microflex Wireless devices running version 1.X firmware must first be updated to version 2.0.5 before being updated to version 3.X or later
- PSM1000 devices with firmware version 1.1.0 or earlier must use Shure Update Utility version 2.4.1 or older
- To update firmware for ULXD6/8 transmitters with ULX-D or QLX-D receivers update receivers to the following minimum
 versions
 - ULXD4, ULXD4D, ULXD4Q Receivers: 2.1.16
 - QLXD4 Receivers: 2.1.5
- Shure Update Utility version 2.4.5 for 32-bit systems is compatible with Wireless Workbench 6 version 6.12.1 and earlier.